

Room #	Item & Location
	East Hall Paint and sheet rock patch
Electrical Room	Panel not labeled Panel front plate not flush seal pass throughs bolt transformer remove excess items in room
Comm Room	Paint clean fix floor tile flex conduit needs to be attached on both ends of A/C u electrical panel not labeled
113	missing firestopping on pass throughs valve tag painted over - clean off hole in epoxy floor near east door exit patch holes/get rid of rust near compressed air line on v finish putting furniture together clean out furniture
110	set up furniture clean out furniture caulk around windows
110A	strobe not flush corner ceiling tile needs to be replaced
janitor room	remove construction debris clean excess paint
115	clean floor remove tape furniture uneven
116	foil on sprinkler heads exposed bolts need to be ground down paint conduit/boxes
117	clean/touch up box patch holes in north wall at top of ceiling missing screw in glass window
106	celan floor paint install benches sesal penetrations repair insulation coming off south side of duct close to 1 need GFCI outlet for washer do plans call for stainless steel sink? bent support rod for fire sprinkler pipe hole in wall in entrance walkway finish sheetrock in entrance walkway

- 106B remove painters tape
 - missing screws around glass window
- 108 scratches in wall
 - fix base cove
 - paint/clean
 - fix/paint drywall
- 104 finish ceiling
 - replace cut ceiling tile
 - paint/clean
 - paint drips at base cove
 - remove cardboard
- 118 set light fixture into frame
 - paint runs
 - does door get door closer?
- 119 remove cover on whiteboard
 - touch up accent wall paint
 - A/V back plate for TVs
 - adjust ceiling tiles
- 103 damaged cabinets
 - loose outlet under sink for garbage disposal
 - install appliances/ ice machines
 - put ceiling tile in
 - adjust door handle
 - adjust light lenses so they fit in frame
- Main Entrance
 - install glass mural/logo
 - replace push button for HVAC
- 140 remove whiteboard cover
 - caulk window
 - ceiling grid dips/uneven at corner of light fixture
- 121 caulk gaps between wall and ceiling grid
 - register broken above main counter
 - roll down cages need to be lockable
 - clean light lenses
- AFFF where is the cabinet for laptop/drawings?
 - paint floor/clean tanks
 - straighten pipes
 - cover for batteries
 - fix sign

Inspection stopped due to reoccurring deficiencies thro

	General Notes
	clean light lenses
	touch up paint
	clean off top of panels
	weather stripping needs to be cleaned on doors
	order covers for strobes
	adjust all door closures
	paint and clean behind man bars
	mortar clean up in hallway
init	remove plastic protectors off everything
	clean out drawers
	controls joints need to be re-done in the hallway
	correct all bathroom deficiencies
wall	Thomas Marks comments
	Mural not installed
	East Entry Comms Door operating sash does nto close; alignment, p
	113 door & frame paint
	exterior entry door - paint
	light switch plate to left (from inside) of exit door - needs larger pla
	drywall repair incomplete
	East Elec R Paint behind column - caulk corners
	door stops missing
	drywall corner unpainted - white
	bolt transformer down
	remove masking from panel; strobe and conduit
	firestop conduit penetration - P 101-0043
	finish masnory at column - ceiling - P 101-0044
Comms	crack in wall
	firestop/caulk feeder conduit penetration for panel TPP2 - P
	cut off all thread at unistruts
	fire stop/caulk behind 4x4 LPIE CKT #1
Rm 113	adjust pipe hangars to bear weight
	drywall repairs incomplete
	main door - frame - paint both sides bumpers missing
	touch up white paint on beige G-line wall
	caulk (fire?) conduit into Comm room wall
L06B	pipe labels
	finish around compressed air piping penetration
	finish penetrations used for temp lighting x 2
	cut off all thread at unistruts
	J box covers not labeled - painted
Rm 114	RA grille plate lifted from grid

		paint - back of door overspray on cove base in SW corner overhead light rattles when door closes eschutcheon plate on door loose
	Hall	terrazo base between rm 110 and janitor - corner broken
	110	trim paint - window, doors frames caulk sill at R window corner
	110A	paint on floor tile caulk door frame header paint interior sash and jamb RA grill rattles when door closes clean, correct, backer rod, caulk window/dry way intersection, trim
	hall at 115	mortar joint at ceiling paint run across hall in 2 course below ceiling - blue tape
	115	TA&B traverse square in duct insulation SA brown paint on epoxy floor at door adjust pipe hangers to bear weight g-line door paint/drywall incomplete corner bead crack sprinkler pipe labeling vault door hits whiteboard tray before contacting stop
	116 Vault	sprinkler brace anchor hole unfinished foil on sprinkler heads door frame hardware rusting; threshold
	118	door hardware inoperable ceiling grid on vault wall RA lifted
	Hall	West of 115 door, paint on floor below receptacle blemish at ceiling of strobe
	Rm 106	Point door hall side some bumpers room side jamb corridor - dry wall incomplete seal temp lighting penetrations and above lockers 3 & 24 caulk around ground bar conduit south wall repair duct insulation at detector repair floor vinyl with scratches, gouges work bench blocking strobe S wall caulk J boxes S wall wall incomplete at corner of 106C - framing visible to R of exit sign cut all thread below UVR finish drywall at penetration above locker 21
throughout building		adjust piping hangers to bear weight; label piping FA conduit hanger all thread too long - curved above lockers
	106C	door - paint, jamb - paint, interior door face and jamb - paint bump repair scratch in epoxy floor no transition strip adjust door closer rate
	106B	finish drywall at window door life frame screws

adjust door to seal; strike to hardware gap
room is labeled 106B - prints label it 107 (106B is the exit door from
108 adjust door closer speed; all painting on door
leaving Rm 108 facing West, ceiling appears to sag on G-line side
104 Tie wire above ceiling is around sprinkler piping P
paint on floor tile
ceiling was open
remove temp lighting wire
remove extra hanging/suspension wire
RA damper radius at take-off not in spec
103 RA not balanced between inlet registers, large whistles
paint on floor tile
appliances not connected to plumbing
light diffuser corner raised

check railing clearances
check door schedule for closer applications, inconsistent along corr

joint

ite; outlet across vestibule

n paint

- P 101-0046

iers

re)

idor